




O-RING  
 P/N P11000-112  
 REPLACES P/N 12-6227N010  
 QTY: 1




GASKET  
 P/N 11-5028N000  
 REPLACES P/N 10-450-28  
 QTY: 1




RETAINING RING  
 P/N P10202-068  
 REPLACES P/N 12-R068S000  
 QTY: 2



TEFLON BACK UP  
 P/N P11227-112  
 REPLACES P/N 12-8774T010  
 QTY: 2



O-RING 90 SHORE  
 P/N P11003-112  
 REPLACES P/N 12-6227N010S  
 QTY: 2



PISTON BUMPER  
 P/N 11-5051P000  
 REPLACES P/N 10-450-51  
 QTY: 1



HELICAL SPRING LOCK WASHER  
 P/N P10212-025  
 REPLACES P/N 12-5001C407  
 QTY: 1

1. COMPONENT PICTURES ARE FULL SCALE  
 DO NOT REDUCE OR ENLARGE WHEN MAKING COPIES OF THIS DOCUMENT



SC HYDRAULIC ENGINEERING CORPORATION  
 BREA, CA 92821

HYDRAULIC REPAIR KIT P/N 11-6099N100  
 REPLACES HYDRAULIC REPAIR KIT P/N 10-550-99-10